

## Report of Analysis

|                    |                             |                 |              |
|--------------------|-----------------------------|-----------------|--------------|
| Client:            | GFE LLC                     | Date Collected: | 02/18/25     |
| Project:           | 97-34 63RD RD, Rego Park NY | Date Received:  | 02/18/25     |
| Client Sample ID:  | IA1A                        | SDG No.:        | Q1386        |
| Lab Sample ID:     | Q1386-01                    | Matrix:         | Air          |
| Analytical Method: | TO-15                       | Test:           | VOCMS Group3 |
| Sample Wt/Vol:     | 400      Units:    mL       |                 |              |

|                   |           |           |                |               |
|-------------------|-----------|-----------|----------------|---------------|
| File ID/Qc Batch: | Dilution: | Prep Date | Date Analyzed  | Prep Batch ID |
| VL042037.D        | 1         |           | 02/21/25 12:47 | VL022125      |

| CAS Number                | Parameter               | Conc.<br>ppbv | Conc.<br>ug/M3 | Qualifier | MDL      | LOQ / CRQL | Units   |
|---------------------------|-------------------------|---------------|----------------|-----------|----------|------------|---------|
| <b>TARGETS</b>            |                         |               |                |           |          |            |         |
| 75-01-4                   | Vinyl Chloride          | 0.010         | 0.030          | U         | 0.030    | 0.080      | ug/m3   |
| 75-35-4                   | 1,1-Dichloroethene      | 0.14          | 0.56           | U         | 0.56     | 1.98       | ug/m3   |
| 156-59-2                  | cis-1,2-Dichloroethene  | 0.21          | 0.83           | J         | 0.36     | 1.98       | ug/m3   |
| 71-55-6                   | 1,1,1-Trichloroethane   | 0.010         | 0.050          | U         | 0.050    | 0.16       | ug/m3   |
| 79-01-6                   | Trichloroethene         | 0.45          | 2.42           |           | 0.11     | 0.16       | ug/m3   |
| 127-18-4                  | Tetrachloroethene       | 10.3          | 69.8           |           | 0.14     | 0.20       | ug/m3   |
| <b>SURROGATES</b>         |                         |               |                |           |          |            |         |
| 460-00-4                  | 1-Bromo-4-Fluorobenzene | 10.5          |                |           | 65 - 135 | 105%       | SPK: 10 |
| <b>INTERNAL STANDARDS</b> |                         |               |                |           |          |            |         |
| 74-97-5                   | Bromochloromethane      | 89400         |                |           | 2.784    |            |         |
| 540-36-3                  | 1,4-Difluorobenzene     | 243000        |                |           | 3.955    |            |         |
| 3114-55-4                 | Chlorobenzene-d5        | 217000        |                |           | 8.878    |            |         |

U = Not Detected

RL = Reporting Limit

MDL = Method Detection Limit

E = Value Exceeds Calibration Range

D = Dilution

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

\* = Values outside of QC limits

Q = indicates LCS control criteria did not meet requirements