

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900, Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 02/20/25 13:15

Project: **Bloomfield Substation** Date Received: 02/20/25

Client Sample ID: TP7 SDG No.: Q1397 Lab Sample ID: Q1397-04

> % Solid: 100

SOIL

Matrix:

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.84	Н	1	0	0	pН		02/24/25 11:10	9045D
Ignitability	NO		1	0	0	oC		02/24/25 09:55	1030
Reactive Cyanide	0.25	U	1	0.044	0.25	mg/Kg	02/21/25 09:00	02/21/25 12:09	9012B
Reactive Sulfide	1.59	J	1	0.19	10.0	mg/Kg	02/24/25 09:00	02/24/25 11:48	9034

Comments: pH result reported at temperature 20.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits