



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.:	Q1410	Order ID:	Q1410
Client:	Homeowner	Project ID:	1355 Cushing Rd Plainfield NJ

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID : KITCHEN-TAP								
Q1410-01	KITCHEN-TAP	Water	Copper	571		1.52	10.0	ug/L
Q1410-01	KITCHEN-TAP	Water	Lead	1.86	J	1.57	6.00	ug/L



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Homeowner	Date Collected:	02/14/25
Project:	1355 Cushing Rd Plainfield NJ	Date Received:	02/21/25
Client Sample ID:	KITCHEN-TAP	SDG No.:	Q1410
Lab Sample ID:	Q1410-01	Matrix:	Water
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-50-8	Copper	571	N	1	1.52	10.0	ug/L	02/24/25 12:05	03/06/25 13:39	EPA 200.7	
7439-92-1	Lead	1.86	J	1	1.57	6.00	ug/L	02/24/25 12:05	03/06/25 13:39	EPA 200.7	

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	Metals Group3			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N =Spiked sample recovery not within control limits



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

LAB CHRONICLE

OrderID:	Q1410	OrderDate:	2/21/2025 1:10:21 PM
Client:	Homeowner	Project:	1355 Cushing Rd Plainfield NJ
Contact:	Charlie Yoon	Location:	N31

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1410-01	KITCHEN-TAP	Water	Metals Group3	200.7	02/14/25	02/24/25	03/06/25	02/21/25