

Report of Analysis

Client:	Weston Solutions, Inc.	Date Collected:	02/24/25 09:50
Project:	RFP 905	Date Received:	02/24/25
Client Sample ID:	P001-CLAY-CF01-02	SDG No.:	Q1421
Lab Sample ID:	Q1421-07	Matrix:	SOIL
		% Solid:	75.2
Parameter	Conc. Qua. DF MDL	LOQ / CRQL Units(Dry Weight) Prep Date	Date Ana. Ana Met.
Cyanide	0.13 J 1 0.057	0.32 mg/Kg 02/25/25 09:00	02/25/25 13:36 9012B

Comments:

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits

^{* =} indicates the duplicate analysis is not within control limits.