

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: G Environmental Date Collected: 02/23/25 16:00 Project: Date Received: Nelson 02/26/25 Client Sample ID: WC1 SDG No.: Q1447 Lab Sample ID: Q1447-02 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ignitability	NO		1	0	0	oC		02/28/25 10:17	1030
Reactive Cyanide	0.042	U	1	0.042	0.24	mg/Kg	02/26/25 16:00	02/27/25 10:07	9012B
Reactive Sulfide	3.16	J	1	0.19	10.0	mg/Kg	02/28/25 08:40	02/28/25 11:23	9034

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits