

Report of Analysis

Client:	Portal Partners Tri-Venture	Date Collected:	03/04/25 09:10
Project:	Amtrak Sawtooth Bridges 2025	Date Received:	03/04/25
Client Sample ID:	ENV-101-SB01	SDG No.:	Q1488
Lab Sample ID:	Q1488-02	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.27	H	1	0	0	pH		03/05/25 16:20	9045D
Ignitability	NO		1	0	0	oC		03/06/25 11:08	1030
Reactive Cyanide	0.042	U	1	0.042	0.24	mg/Kg	03/05/25 11:00	03/05/25 16:22	9012B
Reactive Sulfide	6.30	J	1	0.19	10.0	mg/Kg	03/05/25 15:50	03/06/25 13:30	9034

Comments: pH result reported at temperature 23.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits