

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 03/05/25 09:22 Project: Date Received: Clay St Substation 03/05/25 Client Sample ID: **CLAY-SLUDGE-DRUMS** SDG No.: Q1490 Lab Sample ID: Q1490-01 Matrix: SOIL % Solid: 73.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	it) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.54	U	1	0.11	0.54	mg/Kg	03/07/25 09:00	03/07/25 12:24	7196A
Ignitability	NO		1	0	0	oC		03/06/25 11:52	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		03/06/25 09:30	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits