

## **Report of Analysis**

% Solid: 0	Client Sample ID:	Q1493-01	Matrix:	WATER
	Project: F	DRAIN WATER TANK-1	SDG No.:	Q1493
Client Sample ID: DRAIN WATER TANK-1 SDG No.: Q1493		Floor Drain Water 2025	Date Received:	03/05/25
	Client: N	Major Products	Date Collected:	03/05/25 11:30

Comments:

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

- J = Estimated Value
- B = Analyte Found in Associated Method Blank
- \* = indicates the duplicate analysis is not within control limits.
- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits