

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

ASPHALT-SOIL

## **Report of Analysis**

Client: **PSEG** Date Collected: 03/05/25 10:59

Project: Waldwick Substation Date Received: 03/05/25

Client Sample ID: Lab Sample ID: Q1494-04 Matrix: **SOIL** 

> % Solid: 100

Q1494

SDG No.:

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.55	Н	1	0	0	рН		03/05/25 16:50	9045D
Ignitability	NO		1	0	0	oC		03/06/25 12:15	1030
Reactive Cyanide	0.076	J	1	0.044	0.25	mg/Kg	03/10/25 11:00	03/10/25 15:36	9012B
Reactive Sulfide	3.15	J	1	0.19	10.0	mg/Kg	03/05/25 15:50	03/06/25 13:50	9034

Comments: pH result reported at temperature 23.8 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits