

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Tully Environmental, Inc Date Collected: 03/05/25 11:45 Project: Transfer Station-SPDES Date Received: 03/05/25 Client Sample ID: 002-35TH-AVE(FEB) SDG No.: Q1497 Lab Sample ID: Q1497-02 Matrix: WATER % Solid:

Parameter	Conc. Qu	ıa. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TSS	38.6	1 1.00	4 00	mg/L		03/06/25 10:0	0 SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits