

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Alliance Technical Group, LLC - Newark Date Collected: 03/03/25 Project: NJ Waste Water PT Date Received: 03/05/25 Client Sample ID: PT-SIO2-WP SDG No.: Q1503 Lab Sample ID: Q1503-07 Matrix: Water % Solid: Level (low/med): 0 low

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
Dissolved	Dissolved	199000	D	10	800	8560	ug/L	03/21/25 08:30	04/03/25 13:45	EPA 200.7	7
Silica	Silica										

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Silica

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits