

Report of Analysis

TSS	4.30	1 1.00	4.00	mg/L mg/L		03/10/25 10:00	
TDS	3540	1 1.00	10.0	ma/I		03/06/25 13:30	SM 2540 C-15
Parameter	Conc. Qua	. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
				9/	6 Solid:	0	
Lab Sample ID:	Q1512-01			Matrix:		WATER	
Client Sample ID:	TOWERS	5-1		S	DG No.:	Q1512	
Project:	Linden Generating Station - Towers				Date Received: 03/06/25		
Client:	Parkway Generation Operating LLC				Date Collected:	03/06/25 0	9:58

Comments:

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

- J = Estimated Value
- B = Analyte Found in Associated Method Blank
- * = indicates the duplicate analysis is not within control limits.
- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits