

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Parkway Generation Operating LLC Date Collected: 03/06/25 09:58

Project: Linden Generating Station - Towers Date Received: 03/06/25

Client Sample ID: TOWERS-2 SDG No.: Q1512

Lab Sample ID: Q1512-02 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TDS	3090	1	1.00	10.0	mg/L		03/06/25 13:30	SM 2540 C-15
TSS	4.60	1	1.00	4.00	mg/L		03/10/25 10:00	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits