

 $284 \; Sheffield \; Street, \; Mountainside, \; New \; Jersey \; 07092, \; Phone \; : \; 908 \; 789 \; 8900, \\$ 

Fax: 908 789 8922

## **Report of Analysis**

Client: VERINA CONSULTING GROUP, LLC Date Collected: 03/06/25 10:50

Project: Rotor Clip NJ WTD - 2025 Date Received: 03/06/25

Client Sample ID: WATER TREATMENT DISCHARGE SDG No.: Q1519

Lab Sample ID: Q1519-02 Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Oil and Grease	4.60	J	1 0.40	5.00	mg/L		03/07/25 11:40	) 1664A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits