

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: ENTACT Date Collected: 03/06/25 10:00

Project: 540 Degraw St, Brooklyn, NY - E9309 Date Received: 03/07/25

Client Sample ID: TW-WTS-04DL SDG No.: Q1522

Lab Sample ID: Q1522-02DL Matrix: WATER

% Solid: 0

Parameter	Conc. Qua	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Chloride	68.3 O	R 5 0.055	3.00	mg/L		03/07/25 13:4	2 300.0	

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits