

Report of Analysis

Client:	ENTACT	Date Collected:	03/06/25 11:00
Project:	540 Degraw St, Brooklyn, NY - E9309	Date Received:	03/07/25
Client Sample ID:	WC-A1-02-C	SDG No.:	Q1523
Lab Sample ID:	Q1523-06	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	12.3	H	1	0	0	pH		03/10/25 10:10	9045D
Ignitability	NO		1	0	0	oC		03/10/25 10:00	1030
Reactive Cyanide	0.071	J	1	0.043	0.24	mg/Kg	03/10/25 11:00	03/10/25 15:44	9012B
Reactive Sulfide	6.35	J	1	0.19	10.0	mg/Kg	03/10/25 13:30	03/11/25 08:56	9034

Comments: pH result reported at temperature 24.0 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits