



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.:	Q1540	Order ID:	Q1540
Client:	Nobis Group	Project ID:	Raymark Superfund Site CT 19-NH-95700-

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	LOD	RDL	Units
Client ID :	OU4-CF-15R-031025								
Q1540-01	OU4-CF-15R-031025	Water	Copper	306		14.1	16.0	20.0	ug/L



SAMPLE DATA

Report of Analysis

Client:	Nobis Group	Date Collected:	03/10/25
Project:	Raymark Superfund Site CT 19-NH-95700-001	Date Received:	03/11/25
Client Sample ID:	OU4-CF-15R-031025	SDG No.:	Q1540
Lab Sample ID:	Q1540-01	Matrix:	Water
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-50-8	Copper	306	N	1	14.1	16.0	20.0	ug/L	03/12/25 12:05	03/12/25 14:32	SW6010	SW3010

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	SPLP MetalGroup6			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N =Spiked sample recovery not within control limits



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

LAB CHRONICLE

OrderID:	Q1540	OrderDate:	3/11/2025 10:38:00 AM
Client:	Nobis Group	Project:	Raymark Superfund Site CT 19-NH-95700-001
Contact:	Adam Roy	Location:	I31

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1540-01	OU4-CF-15R-031025	Water	SPLP MetalGroup6	6010D	03/10/25	03/12/25	03/12/25	03/11/25