

Report of Analysis

Client:	Weston Solutions	Date Collected:	03/11/25 12:55
Project:	Fort Meade MD Tipton Airfield Parcel RI - 0111169	Date Received:	03/12/25
Client Sample ID:	TAPLPR-SED13-031125-00-T2	SDG No.:	Q1548
Lab Sample ID:	Q1548-02	Matrix:	SOIL
		% Solid:	55.5

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
pH	5.63	H	1	0	0	0	pH		03/13/25 09:25	9045D
TOC	15500	OR	1	28.9	50.0	250	mg/Kg		03/20/25 11:08	9060A

Comments: pH result reported at temperature 21.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits