

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

% Solid:

100

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 03/13/25 13:18 Project: Jersey City Gas District Date Received: 03/13/25 Client Sample ID: JC-03-03132025 SDG No.: Q1568 Lab Sample ID: Q1568-04 Matrix: SOIL

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.97	Н	1	0	0	рН		03/14/25 15:15	9045D
Ignitability	NO		1	0	0	oC		03/14/25 12:16	1030
Reactive Cyanide	0.25	U	1	0.044	0.25	mg/Kg	03/14/25 14:00	03/14/25 15:50	9012B
Reactive Sulfide	1.59	J	1	0.20	10.0	mg/Kg	03/17/25 15:20	03/18/25 11:48	9034

Comments: pH result reported at temperature 23.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits