

Report of Analysis

Client:	Weston Solutions	Date Collected:	03/13/25 10:50
Project:	Fort Meade MD Tipton Airfield Parcel RI - 0111169	Date Received:	03/14/25
Client Sample ID:	TAP-IDW-SOIL-031325-02	SDG No.:	Q1569
Lab Sample ID:	Q1569-04	Matrix:	SOIL
		% Solid:	73.3

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.26	U	1	0.054	0.26	0.32	mg/Kg	03/20/25 10:00	03/21/25 10:48	9012B
Ignitability	NO		1	0	0	0	oC		03/14/25 12:31	1030
pH	10.2	H	1	0	0	0	pH		03/14/25 15:20	9045D
Sulfide	6.79	U	1	2.73	6.79	13.6	mg/Kg	03/19/25 13:40	03/19/25 16:03	9034

Comments: pH result reported at temperature 21.5 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits