

Initial and Continuing Calibration Verification

Client: G Environmental

SDG No.: Q1574

Project: Ave L

RunNo.: LB135039

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
pH		pH	6.99	7	100	90-110	03/14/2025
Sample ID:	CCV1						
pH		pH	2.01	2.00	101	90-110	03/14/2025
Sample ID:	CCV2						
pH		pH	12.02	12.00	100	90-110	03/14/2025

Initial and Continuing Calibration Verification

Client: G Environmental

SDG No.: Q1574

Project: Ave L

RunNo.: LB135040

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
Corrosivity		pH	6.99	7	100	90-110	03/14/2025
Sample ID:	CCV1						
Corrosivity		pH	2.01	2.00	101	90-110	03/14/2025
Sample ID:	CCV2						
Corrosivity		pH	12.02	12.00	100	90-110	03/14/2025

Initial and Continuing Calibration Verification

Client: G Environmental

SDG No.: Q1574

Project: Ave L

RunNo.: LB135043

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.092	0.099	93	85-115	03/14/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/14/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/14/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	03/14/2025