

Lab Sample ID:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Matrix:

SOIL

Fax: 908 789 8922

Q1606-08

## **Report of Analysis**

Client: PSEG Date Collected: 03/19/25 11:05

Project: 414 Grand Street Gas Pipe Repair Date Received: 03/19/25

Client Sample ID: RT3025 SDG No.: Q1606

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.08	Н	1	0	0	pН		03/20/25 16:47	9045D
Ignitability	NO		1	0	0	oC		03/24/25 16:40	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	03/20/25 14:10	03/20/25 16:32	9012B
Reactive Sulfide	1.58	J	1	0.20	10.0	mg/Kg	03/21/25 10:10	03/21/25 12:55	9034

Comments: pH result reported at temperature 22.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits