

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 03/20/25 Project: Date Received: 03/20/25 Port St- Newark Project Client Sample ID: CONCRETE-2 SDG No.: Q1619 Lab Sample ID: Q1619-03 Matrix: SOIL % Solid: 100 Level (low/med): low

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units(Dry W	/eigh P)rep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	4.31	1 0.13	0.50	mg/Kg	03/21/25 10:15	03/25/25 12:15	SW6010	SW3050

Color Before: Brown Clarity Before: Texture: Medium

Color After: Yellow Clarity After: Artifacts:

Comments: Metals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits