

LAB CHRONICLE

OrderID:	Q1626	OrderDate:	3/21/2025 12:59:00 PM
Client:	Walsh Construction Company II, LLC	Project:	Walsh CO-032 Sampling
Contact:	Evelyne Benie Dion Gokan	Location:	F11,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1626-01	CO-32-1	SOIL			03/21/25 11:20			03/21/25
			Ammonia	SM4500-NH3		03/25/25	03/25/25 12:28	
			COD	SM5220 D			03/25/25 15:07	
			Cyanide	9012B		03/25/25	03/25/25 16:34	
			Hexavalent Chromium	7196A		03/24/25	03/24/25 15:28	
			Oil and Grease	9071B			03/25/25 09:30	
			Paint Filter	9095B			03/25/25 09:38	
			TS	SM2540 B			03/24/25 12:00	
			TVS	160.4			03/24/25 16:25	
Q1626-03	CO-32-1	SOIL			03/21/25 11:20			03/21/25
			Corrosivity	9045D			03/24/25 16:55	
			Ignitability	1030			03/24/25 11:38	
			Reactive Cyanide	9012B		03/25/25	03/25/25 15:45	
			Reactive Sulfide	9034		03/25/25	03/25/25 11:33	



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	03/21/25 11:20
Project:	Walsh CO-032 Sampling	Date Received:	03/21/25
Client Sample ID:	CO-32-1	SDG No.:	Q1626
Lab Sample ID:	Q1626-01	Matrix:	SOIL
		% Solid:	94.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Ammonia as N	2.30	U	1	2.30	5.20	mg/Kg	03/25/25 08:50	03/25/25 12:28	SM 4500-NH3 B plus G-11
COD	7640	D	5	435	2590	mg/Kg		03/25/25 15:07	SM 5220 D-11
Cyanide	0.043	U	1	0.043	0.26	mg/Kg	03/25/25 13:30	03/25/25 16:34	9012B
Hexavalent Chromium	0.069	U	1	0.069	0.40	mg/Kg	03/24/25 10:15	03/24/25 15:28	7196A
Oil and Grease	1930		1	6.12	26.3	mg/Kg		03/25/25 09:30	SW9071B
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		03/25/25 09:38	9095B
TS	94.8		1	1.00	5.00	%		03/24/25 12:00	SM 2540 B-15
TVS	2.70	J	1	1.00	10.0	%		03/24/25 16:25	160.4

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	03/21/25 11:20
Project:	Walsh CO-032 Sampling	Date Received:	03/21/25
Client Sample ID:	CO-32-1	SDG No.:	Q1626
Lab Sample ID:	Q1626-03	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.27	H	1	0	0	pH		03/24/25 16:55	9045D
Ignitability	NO		1	0	0	oC		03/24/25 11:38	1030
Reactive Cyanide	0.0083	U	1	0.0083	0.050	mg/Kg	03/25/25 11:30	03/25/25 15:45	9012B
Reactive Sulfide	1.59	J	1	0.20	10.0	mg/Kg	03/25/25 09:20	03/25/25 11:33	9034

Comments: pH result reported at temperature 22.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits

QC RESULT SUMMARY

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135159

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.492	0.5	98	90-110	03/24/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.489	0.5	98	90-110	03/24/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.494	0.5	99	90-110	03/24/2025
Sample ID: CCV3 Hexavalent Chromium	mg/L	0.496	0.5	99	90-110	03/24/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135166

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Corrosivity	pH	7.00	7	100	90-110	03/24/2025
Sample ID: CCV1 Corrosivity	pH	2.01	2.00	101	90-110	03/24/2025
Sample ID: CCV2 Corrosivity	pH	12.02	12.00	100	90-110	03/24/2025
Sample ID: CCV3 Corrosivity	pH	2.01	2.00	101	90-110	03/24/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135176

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Ammonia as N	mg/L	1	1	100	90-110	03/25/2025
Sample ID: CCV1 Ammonia as N	mg/L	1	1	100	90-110	03/25/2025
Sample ID: CCV2 Ammonia as N	mg/L	0.98	1	98	90-110	03/25/2025
Sample ID: CCV3 Ammonia as N	mg/L	1	1	100	90-110	03/25/2025
Sample ID: CCV4 Ammonia as N	mg/L	0.98	1	98	90-110	03/25/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135178

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV COD	mg/L	49.329	50	99	95-105	01/22/2025
Sample ID: CCV1 COD	mg/L	50.319	50	101	95-105	03/25/2025
Sample ID: CCV2 COD	mg/L	49.329	50	99	95-105	03/25/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135179

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.094	0.099	95	85-115	03/25/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV4 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135181

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Cyanide	mg/L	0.096	0.099	97	90-110	03/25/2025
Sample ID: CCV1 Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV2 Cyanide	mg/L	0.25	0.25	100	90-110	03/25/2025

Initial and Continuing Calibration Blank Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135159

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB Hexavalent Chromium	mg/L	< 0.0050	0.0050	U	0.0029	0.01	03/24/2025
Sample ID: CCB1 Hexavalent Chromium	mg/L	< 0.0050	0.0050	U	0.0029	0.01	03/24/2025
Sample ID: CCB2 Hexavalent Chromium	mg/L	< 0.0050	0.0050	U	0.0029	0.01	03/24/2025
Sample ID: CCB3 Hexavalent Chromium	mg/L	< 0.0050	0.0050	U	0.0029	0.01	03/24/2025

Initial and Continuing Calibration Blank Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135176

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB1 Ammonia as N	mg/L	< 0.0500	0.0500	U	0.030	0.1	03/25/2025
Sample ID: CCB1 Ammonia as N	mg/L	< 0.0500	0.0500	U	0.030	0.1	03/25/2025
Sample ID: CCB2 Ammonia as N	mg/L	0.037	0.0500	J	0.030	0.1	03/25/2025
Sample ID: CCB3 Ammonia as N	mg/L	< 0.0500	0.0500	U	0.030	0.1	03/25/2025
Sample ID: CCB4 Ammonia as N	mg/L	< 0.0500	0.0500	U	0.030	0.1	03/25/2025

Initial and Continuing Calibration Blank Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135178

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB COD	mg/L	< 5.0000	5.0000	U	1.50	10	01/22/2025
Sample ID: CCB1 COD	mg/L	< 5.0000	5.0000	U	1.50	10	03/25/2025
Sample ID: CCB2 COD	mg/L	< 5.0000	5.0000	U	1.50	10	03/25/2025

Initial and Continuing Calibration Blank Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135179

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB1 Reactive Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	03/25/2025
Sample ID: CCB1 Reactive Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	03/25/2025
Sample ID: CCB2 Reactive Cyanide	mg/L	0.00096	0.0025	J	0.00096	0.005	03/25/2025
Sample ID: CCB3 Reactive Cyanide	mg/L	0.001	0.0025	J	0.00096	0.005	03/25/2025
Sample ID: CCB4 Reactive Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	03/25/2025

Initial and Continuing Calibration Blank Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135181

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB1 Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	03/25/2025
Sample ID: CCB1 Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	03/25/2025
Sample ID: CCB2 Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	03/25/2025

Preparation Blank Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: LB135161BL TS	%	< 2.5000	2.5000	U	1	5	03/24/2025
Sample ID: LB135162BL TVS	%	< 5.0000	5.0000	U	1	10	03/24/2025
Sample ID: LB135168BL Oil and Grease	mg/Kg	< 12.5000	12.5000	U	5.8	25	03/25/2025
Sample ID: LB135178BL COD	mg/Kg	< 250.0000	250.0000	U	84.1	500	03/25/2025
Sample ID: PB167259BL Hexavalent Chromium	mg/Kg	< 0.2000	0.2000	U	0.07	0.4	03/24/2025
Sample ID: PB167281BL Ammonia as N	mg/Kg	< 2.5000	2.5000	U	2.2	5	03/25/2025
Sample ID: PB167287BL Reactive Sulfide	mg/Kg	< 5.0000	5.0000	U	0.201	10	03/25/2025
Sample ID: PB167300BL Reactive Cyanide	mg/Kg	< 0.0250	0.0250	U	0.0084	0.05	03/25/2025
Sample ID: PB167306BL Cyanide	mg/Kg	< 0.1250	0.1250	U	0.042	0.25	03/25/2025

Matrix Spike Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1614-01
Client ID:	TR-04-032025MS	Percent Solids for Spike Sample:	94.6

Analyte	Units	Acceptance Limit %R	Spiked Result	Conc. Qualifier	Sample Result	Conc. Qualifier	Spike Added	Dilution Factor	% Rec	Qual	Analysis Date
Hexavalent Chromium	mg/Kg	75-125	1290		0.073	U	1360	40	95		03/24/2025

Matrix Spike Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1614-01
Client ID:	TR-04-032025MS	Percent Solids for Spike Sample:	94.6

Analyte	Units	Acceptance Limit %R	Spiked Result	Conc. Qualifier	Sample Result	Conc. Qualifier	Spike Added	Dilution Factor	% Rec	Qual	Analysis Date
Hexavalent Chromium	mg/Kg	85-115	39.0		0.073	U	42.3	2	92		03/24/2025

Matrix Spike Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1614-01
Client ID:	TR-04-032025MS	Percent Solids for Spike Sample:	94.6

Analyte	Units	Acceptance Limit %R	Spiked Result	Conc. Qualifier	Sample Result	Conc. Qualifier	Spike Added	Dilution Factor	% Rec	Qual	Analysis Date
Hexavalent Chromium	mg/Kg	75-125	33.0		0.073	U	42.3	2	78		03/24/2025

Matrix Spike Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1626-01
Client ID:	CO-32-1MS	Percent Solids for Spike Sample:	94.8

Analyte	Units	Acceptance Limit %R	Spiked Result	Conc. Qualifier	Sample Result	Conc. Qualifier	Spike Added	Dilution Factor	% Rec	Qual	Analysis Date
Cyanide	mg/Kg	75-125	1.70		0.043	U	2.1	1	81		03/25/2025

Matrix Spike Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1626-01
Client ID:	CO-32-1MSD	Percent Solids for Spike Sample:	94.8

Analyte	Units	Acceptance Limit %R	Spiked Result	Conc. Qualifier	Sample Result	Conc. Qualifier	Spike Added	Dilution Factor	% Rec	Qual	Analysis Date
Cyanide	mg/Kg	75-125	1.70		0.043	U	2.1	1	81		03/25/2025

Matrix Spike Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1632-01
Client ID:	PIER-1-2MS	Percent Solids for Spike Sample:	95.4

Analyte	Units	Acceptance Limit %R	Spiked Result	Conc. Qualifier	Sample Result	Conc. Qualifier	Spike Added	Dilution Factor	% Rec	Qual	Analysis Date
Oil and Grease	mg/Kg	75-125	36.6		20.9	J	105	1	15	*	03/25/2025
COD	mg/Kg	75-125	4570		2090		2570	1	96		03/25/2025
Ammonia as N	mg/Kg	75-125	53.2		2.20	U	51.4	1	104		03/25/2025

Matrix Spike Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1632-01
Client ID:	PIER-1-2MSD	Percent Solids for Spike Sample:	95.4

Analyte	Units	Acceptance Limit %R	Spiked Result	Conc. Qualifier	Sample Result	Conc. Qualifier	Spike Added	Dilution Factor	% Rec	Qual	Analysis Date
Oil and Grease	mg/Kg	75-125	52.3		20.9	J	105	1	30	*	03/25/2025
COD	mg/Kg	75-125	4470		2090		2570	1	93		03/25/2025
Ammonia as N	mg/Kg	75-125	52.5		2.20	U	50.9	1	103		03/25/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1610-02
Client ID:	SOIL-PILEDUP	Percent Solids for Spike Sample:	86.5

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Ignitability	oC	+/-20	NO		NO		1	0		03/24/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1614-01
Client ID:	TR-04-032025DUP	Percent Solids for Spike Sample:	94.6

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/AD	Qual	Analysis Date
Hexavalent Chromium	mg/Kg	+/-20	0.073	U	0.073	U	1	0		03/24/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1619-06
Client ID:	TP-1DUP	Percent Solids for Spike Sample:	100

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/AD	Qual	Analysis Date
Reactive Cyanide	mg/Kg	+/-20	0.0083	U	0.0084	U	1	0		03/25/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1626-01
Client ID:	CO-32-1DUP	Percent Solids for Spike Sample:	100

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/AD	Qual	Analysis Date
TS	%	+/-5	94.8		95.2		1	0.42		03/24/2025
TVS	%	+/-5	2.70	J	2.60	J	1	3.77		03/24/2025

Duplicate Sample Summary

Client: Walsh Construction Company II, LLC	SDG No.: Q1626
Project: Walsh CO-032 Sampling	Sample ID: Q1626-01
Client ID: CO-32-1DUP	Percent Solids for Spike Sample: 94.8

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Cyanide	mg/Kg	+/-20	0.043	U	0.044	U	1	0		03/25/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1626-01
Client ID:	CO-32-1MSD	Percent Solids for Spike Sample:	94.8

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Cyanide	mg/Kg	+/-20	1.70		1.70		1	0		03/25/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1626-03
Client ID:	CO-32-1DUP	Percent Solids for Spike Sample:	100

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Reactive Sulfide	mg/Kg	+/-20	1.59	J	1.59	J	1	0		03/25/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1632-01
Client ID:	PIER-1-2DUP	Percent Solids for Spike Sample:	95.4

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/AD	Qual	Analysis Date
Oil and Grease	mg/Kg	+/-20	20.9	J	20.9	J	1	0.05		03/25/2025
Ammonia as N	mg/Kg	+/-20	2.20	U	2.20	U	1	0		03/25/2025
COD	mg/Kg	+/-20	2090		2210		1	5.58		03/25/2025

Duplicate Sample Summary

Client: Walsh Construction Company II, LLC	SDG No.: Q1626
Project: Walsh CO-032 Sampling	Sample ID: Q1632-01
Client ID: PIER-1-2MSD	Percent Solids for Spike Sample: 95.4

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/AD	Qual	Analysis Date
Oil and Grease	mg/Kg	+/-20	36.6		52.3		1	35.3	*	03/25/2025
Ammonia as N	mg/Kg	+/-20	53.2		52.5		1	1		03/25/2025
COD	mg/Kg	+/-20	4570		4470		1	2.21		03/25/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1632-02
Client ID:	PIER-1-2DUP	Percent Solids for Spike Sample:	100

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/AD	Qual	Analysis Date
Corrosivity	pH	+/-20	10.6		10.6		1	0.09		03/24/2025

Duplicate Sample Summary

Client:	Walsh Construction Company II, LLC	SDG No.:	Q1626
Project:	Walsh CO-032 Sampling	Sample ID:	Q1635-01
Client ID:	TP-2DUP	Percent Solids for Spike Sample:	89.4

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Paint Filter	ml/100gm	+/-20	1.00	U	1.00	U	1	0		03/25/2025

Laboratory Control Sample Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

Run No.: LB135168

Analyte	Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	LB135168BS							
Oil and Grease	mg/Kg	100	94.9		95	1	80-120	03/25/2025

Laboratory Control Sample Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

Run No.: LB135178

Analyte	Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	LB135178BS							
COD	mg/Kg	2500	2470		99	1	90-110	03/25/2025

Laboratory Control Sample Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

Run No.: LB135159

Analyte	Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	PB167259BS							
Hexavalent Chromium	mg/Kg	20	19.9		100	1	84-110	03/24/2025

Laboratory Control Sample Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

Run No.: LB135176

Analyte	Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	PB167281BS							
Ammonia as N	mg/Kg	50	53.1		106	1	90-110	03/25/2025

Laboratory Control Sample Summary

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

Run No.: LB135181

Analyte	Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	PB167306BS							
Cyanide	mg/Kg	5	4.70		94	1	85-115	03/25/2025