



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135159

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.492	0.5	98	90-110	03/24/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.489	0.5	98	90-110	03/24/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.494	0.5	99	90-110	03/24/2025
Sample ID: CCV3 Hexavalent Chromium	mg/L	0.496	0.5	99	90-110	03/24/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135166

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.00	7	100	90-110	03/24/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90-110	03/24/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	03/24/2025
Sample ID: Corrosivity	CCV3	pH	2.01	2.00	101	90-110	03/24/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135176

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Ammonia as N	mg/L	1	1	100	90-110	03/25/2025
Sample ID: CCV1 Ammonia as N	mg/L	1	1	100	90-110	03/25/2025
Sample ID: CCV2 Ammonia as N	mg/L	0.98	1	98	90-110	03/25/2025
Sample ID: CCV3 Ammonia as N	mg/L	1	1	100	90-110	03/25/2025
Sample ID: CCV4 Ammonia as N	mg/L	0.98	1	98	90-110	03/25/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135178

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV COD	mg/L	49.329	50	99	95-105	01/22/2025
Sample ID: CCV1 COD	mg/L	50.319	50	101	95-105	03/25/2025
Sample ID: CCV2 COD	mg/L	49.329	50	99	95-105	03/25/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135179

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.094	0.099	95	85-115	03/25/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV4 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1626

Project: Walsh CO-032 Sampling

RunNo.: LB135181

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Cyanide	mg/L	0.096	0.099	97	90-110	03/25/2025
Sample ID: CCV1 Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV2 Cyanide	mg/L	0.25	0.25	100	90-110	03/25/2025