

Surrogate Summary

SW-846

SDG No.: Q1626

Client: Walsh Construction Company II, LLC

Analytical Method: 8270E

Lab Sample ID	Client ID	Parameter	Spike (PPM)	Result (PPM)	Recovery (%)	Qual	Limits (%)	
							Low	High
PB167274BL	PB167274BL	2-Fluorophenol	150	146	97		18	112
		Phenol-d6	150	139	93		15	107
		Nitrobenzene-d5	100	99.8	100		18	107
		2-Fluorobiphenyl	100	99.5	100		20	109
		2,4,6-Tribromophenol	150	169	113		10	116
		Terphenyl-d14	100	125	125	*	10	105
PB167274BS	PB167274BS	2-Fluorophenol	150	151	101		18	112
		Phenol-d6	150	147	98		15	107
		Nitrobenzene-d5	100	104	104		18	107
		2-Fluorobiphenyl	100	104	104		20	109
		2,4,6-Tribromophenol	150	184	123	*	10	116
		Terphenyl-d14	100	129	129	*	10	105
Q1626-01	CO-32-1	2-Fluorophenol	150	105	70		18	112
		Phenol-d6	150	94.6	63		15	107
		Nitrobenzene-d5	100	78.7	79		18	107
		2-Fluorobiphenyl	100	85.3	85		20	109
		2,4,6-Tribromophenol	150	112	75		10	116
		Terphenyl-d14	100	61.4	61		10	105
Q1626-01MS	CO-32-1MS	2-Fluorophenol	150	102	68		18	112
		Phenol-d6	150	94.1	63		15	107
		Nitrobenzene-d5	100	77.2	77		18	107
		2-Fluorobiphenyl	100	84.0	84		20	109
		2,4,6-Tribromophenol	150	113	75		10	116
		Terphenyl-d14	100	69.2	69		10	105
Q1626-01MSD	CO-32-1MSD	2-Fluorophenol	150	100	67		18	112
		Phenol-d6	150	92.1	61		15	107
		Nitrobenzene-d5	100	73.8	74		18	107
		2-Fluorobiphenyl	100	78.7	79		20	109
		2,4,6-Tribromophenol	150	118	79		10	116
		Terphenyl-d14	100	75.6	76		10	105