



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.: Q1627

Client: Tully Construction Co., Inc.

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID:	GRID-LINE-1.2-NORTH							
Q1627-01	GRID-LINE-1.2-NORTH TCLP		2-Butanone	9.70	J	0.98	25.0	ug/L
			Total Voc :	9.70				
			Total Concentration:	9.70				



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.	Date Collected:	03/20/25
Project:	DOT Harper Street Yard - North Side	Date Received:	03/21/25
Client Sample ID:	GRID-LINE-1.2-NORTH	SDG No.:	Q1627
Lab Sample ID:	Q1627-01	Matrix:	TCLP
Analytical Method:	SW8260	% Solid:	0
Sample Wt/Vol:	5 Units: mL	Final Vol:	5000 uL
Soil Aliquot Vol:	uL	Test:	TCLP VOA
GC Column:	RXI-624 ID : 0.25	Level :	LOW
Prep Method :	SW5035		

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
VN086112.D	1		03/25/25 19:52	VN032525

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
75-01-4	Vinyl Chloride	0.26	U	0.26	5.00	ug/L
75-35-4	1,1-Dichloroethene	0.23	U	0.23	5.00	ug/L
78-93-3	2-Butanone	9.70	J	0.98	25.0	ug/L
56-23-5	Carbon Tetrachloride	0.25	U	0.25	5.00	ug/L
67-66-3	Chloroform	0.25	U	0.25	5.00	ug/L
71-43-2	Benzene	0.15	U	0.15	5.00	ug/L
107-06-2	1,2-Dichloroethane	0.22	U	0.22	5.00	ug/L
79-01-6	Trichloroethene	0.090	U	0.090	5.00	ug/L
127-18-4	Tetrachloroethene	0.23	U	0.23	5.00	ug/L
108-90-7	Chlorobenzene	0.12	U	0.12	5.00	ug/L
SURROGATES						
17060-07-0	1,2-Dichloroethane-d4	56.1		74 - 125	112%	SPK: 50
1868-53-7	Dibromofluoromethane	52.3		75 - 124	105%	SPK: 50
2037-26-5	Toluene-d8	51.9		86 - 113	104%	SPK: 50
460-00-4	4-Bromofluorobenzene	45.1		77 - 121	90%	SPK: 50
INTERNAL STANDARDS						
363-72-4	Pentafluorobenzene	166000	8.224			
540-36-3	1,4-Difluorobenzene	311000	9.1			
3114-55-4	Chlorobenzene-d5	301000	11.865			
3855-82-1	1,4-Dichlorobenzene-d4	115000	13.788			

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

() = Laboratory InHouse Limit

A = Aldol-Condensation Reaction Products



LAB CHRONICLE

OrderID:	Q1627	OrderDate:	3/21/2025 1:34:14 PM
Client:	Tully Construction Co., Inc.	Project:	DOT Harper Street Yard - North Side
Contact:	Dean Devoe	Location:	I41

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1627-01	GRID-LINE-1.2-NORT H	TCLP	TCLP VOA	8260D	03/20/25		03/25/25	03/21/25



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

A

B

C

D

Hit Summary Sheet SW-846

SDG No.: Q1627
Client: Tully Construction Co., Inc.

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID :				0.000				
Total Svoc :					0.00			
Total Concentration:					0.00			



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.	Date Collected:	03/25/25
Project:	DOT Harper Street Yard - North Side	Date Received:	03/25/25
Client Sample ID:	PB167275TB	SDG No.:	Q1627
Lab Sample ID:	PB167275TB	Matrix:	TCLP
Analytical Method:	SW8270	% Solid:	0
Sample Wt/Vol:	100 Units: mL	Final Vol:	1000 uL
Soil Aliquot Vol:	uL	Test:	TCLP BNA
Extraction Type :	Decanted : N	Level :	LOW
Injection Volume :	GPC Factor : 1.0	GPC Cleanup :	N PH :
Prep Method :	SW3541		

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
BF142097.D	1	03/25/25 12:25	03/26/25 15:06	PB167310

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
110-86-1	Pyridine	12.8	U	12.8	50.0	ug/L
106-46-7	1,4-Dichlorobenzene	5.30	U	5.30	50.0	ug/L
95-48-7	2-Methylphenol	11.2	U	11.2	50.0	ug/L
65794-96-9	3+4-Methylphenols	11.0	U	11.0	100	ug/L
67-72-1	Hexachloroethane	6.50	U	6.50	50.0	ug/L
98-95-3	Nitrobenzene	7.60	U	7.60	50.0	ug/L
87-68-3	Hexachlorobutadiene	5.40	UQ	5.40	50.0	ug/L
88-06-2	2,4,6-Trichlorophenol	5.10	U	5.10	50.0	ug/L
95-95-4	2,4,5-Trichlorophenol	6.20	U	6.20	50.0	ug/L
121-14-2	2,4-Dinitrotoluene	12.2	UQ	12.2	50.0	ug/L
118-74-1	Hexachlorobenzene	5.20	UQ	5.20	50.0	ug/L
87-86-5	Pentachlorophenol	15.8	U	15.8	100	ug/L
SURROGATES						
367-12-4	2-Fluorophenol	147		10 - 139	98%	SPK: 150
13127-88-3	Phenol-d6	138		10 - 134	92%	SPK: 150
4165-60-0	Nitrobenzene-d5	102		49 - 133	102%	SPK: 100
321-60-8	2-Fluorobiphenyl	103		52 - 132	103%	SPK: 100
118-79-6	2,4,6-Tribromophenol	161		44 - 137	107%	SPK: 150
1718-51-0	Terphenyl-d14	110		48 - 125	110%	SPK: 100
INTERNAL STANDARDS						
3855-82-1	1,4-Dichlorobenzene-d4	124000	6.869			
1146-65-2	Naphthalene-d8	481000	8.151			
15067-26-2	Acenaphthene-d10	269000	9.91			
1517-22-2	Phenanthrene-d10	489000	11.392			
1719-03-5	Chrysene-d12	341000	14.033			
1520-96-3	Perylene-d12	285000	15.51			

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:	03/25/25	
Project:	DOT Harper Street Yard - North Side		Date Received:	03/25/25	
Client Sample ID:	PB167275TB		SDG No.:	Q1627	
Lab Sample ID:	PB167275TB		Matrix:	TCLP	
Analytical Method:	SW8270		% Solid:	0	
Sample Wt/Vol:	100	Units: mL	Final Vol:	1000	uL
Soil Aliquot Vol:		uL	Test:	TCLP BNA	
Extraction Type :		Decanted : N	Level :	LOW	
Injection Volume :		GPC Factor : 1.0	GPC Cleanup :	N	PH :
Prep Method :	SW3541				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
BF142097.D	1	03/25/25 12:25	03/26/25 15:06	PB167310

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
------------	-----------	-------	-----------	-----	------------	-------

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

() = Laboratory InHouse Limit

A = Aldol-Condensation Reaction Products

Report of Analysis

Client:	Tully Construction Co., Inc.	Date Collected:	03/20/25
Project:	DOT Harper Street Yard - North Side	Date Received:	03/21/25
Client Sample ID:	GRID-LINE-1.2-NORTH	SDG No.:	Q1627
Lab Sample ID:	Q1627-01	Matrix:	TCLP
Analytical Method:	SW8270	% Solid:	0
Sample Wt/Vol:	100 Units: mL	Final Vol:	1000 uL
Soil Aliquot Vol:	uL	Test:	TCLP BNA
Extraction Type :	Decanted : N	Level :	LOW
Injection Volume :	GPC Factor : 1.0	GPC Cleanup :	N PH :
Prep Method :	SW3541		

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
BF142085.D	1	03/25/25 12:25	03/25/25 18:38	PB167310

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
110-86-1	Pyridine	12.8	U	12.8	50.0	ug/L
106-46-7	1,4-Dichlorobenzene	5.30	U	5.30	50.0	ug/L
95-48-7	2-Methylphenol	11.2	U	11.2	50.0	ug/L
65794-96-9	3+4-Methylphenols	11.0	U	11.0	100	ug/L
67-72-1	Hexachloroethane	6.50	U	6.50	50.0	ug/L
98-95-3	Nitrobenzene	7.60	U	7.60	50.0	ug/L
87-68-3	Hexachlorobutadiene	5.40	UQ	5.40	50.0	ug/L
88-06-2	2,4,6-Trichlorophenol	5.10	U	5.10	50.0	ug/L
95-95-4	2,4,5-Trichlorophenol	6.20	U	6.20	50.0	ug/L
121-14-2	2,4-Dinitrotoluene	12.2	UQ	12.2	50.0	ug/L
118-74-1	Hexachlorobenzene	5.20	UQ	5.20	50.0	ug/L
87-86-5	Pentachlorophenol	15.8	U	15.8	100	ug/L
SURROGATES						
367-12-4	2-Fluorophenol	151		10 - 139	101%	SPK: 150
13127-88-3	Phenol-d6	136		10 - 134	91%	SPK: 150
4165-60-0	Nitrobenzene-d5	115		49 - 133	115%	SPK: 100
321-60-8	2-Fluorobiphenyl	114		52 - 132	114%	SPK: 100
118-79-6	2,4,6-Tribromophenol	196		44 - 137	131%	SPK: 150
1718-51-0	Terphenyl-d14	153	*	48 - 125	153%	SPK: 100
INTERNAL STANDARDS						
3855-82-1	1,4-Dichlorobenzene-d4	148000		6.875		
1146-65-2	Naphthalene-d8	578000		8.151		
15067-26-2	Acenaphthene-d10	329000		9.904		
1517-22-2	Phenanthrene-d10	562000		11.392		
1719-03-5	Chrysene-d12	280000		14.033		
1520-96-3	Perylene-d12	235000		15.504		

Report of Analysis

Client:	Tully Construction Co., Inc.	Date Collected:	03/20/25
Project:	DOT Harper Street Yard - North Side	Date Received:	03/21/25
Client Sample ID:	GRID-LINE-1.2-NORTH	SDG No.:	Q1627
Lab Sample ID:	Q1627-01	Matrix:	TCLP
Analytical Method:	SW8270	% Solid:	0
Sample Wt/Vol:	100 Units: mL	Final Vol:	1000 uL
Soil Aliquot Vol:	uL	Test:	TCLP BNA
Extraction Type :	Decanted : N	Level :	LOW
Injection Volume :	GPC Factor : 1.0	GPC Cleanup :	N PH :
Prep Method :	SW3541		

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
BF142085.D	1	03/25/25 12:25	03/25/25 18:38	PB167310

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
------------	-----------	-------	-----------	-----	------------	-------

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

() = Laboratory InHouse Limit

A = Aldol-Condensation Reaction Products



LAB CHRONICLE

OrderID:	Q1627	OrderDate:	3/21/2025 1:34:14 PM
Client:	Tully Construction Co., Inc.	Project:	DOT Harper Street Yard - North Side
Contact:	Dean Devoe	Location:	I41

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1627-01	GRID-LINE-1.2-NORTH	TCLP	TCLP BNA	8270E	03/20/25	03/25/25	03/25/25	03/21/25



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.: Q1627

Order ID: Q1627

Client: Tully Construction Co., Inc.

Project ID: DOT Harper Street Yard - North Side

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
-----------	-----------	--------	-----------	---------------	---	-----	-----	-------

Client ID :

Total Concentration: 0.000

A
B
C
D



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:		
Project:	DOT Harper Street Yard - North Side		Date Received:	03/25/25	
Client Sample ID:	PB167275TB		SDG No.:	Q1627	
Lab Sample ID:	PB167275TB		Matrix:	TCLP	
Analytical Method:	SW8081		% Solid:	0	Decanted:
Sample Wt/Vol:	100	Units: mL	Final Vol:	10000	uL
Soil Aliquot Vol:		uL	Test:	TCLP Pesticide	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	SW3541B				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PL094855.D	1	03/25/25 12:40	03/25/25 20:12	PB167311

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
58-89-9	gamma-BHC (Lindane)	0.037	U	0.037	0.50	ug/L
76-44-8	Heptachlor	0.027	U	0.027	0.50	ug/L
1024-57-3	Heptachlor epoxide	0.096	U	0.096	0.50	ug/L
72-20-8	Endrin	0.032	U	0.032	0.50	ug/L
72-43-5	Methoxychlor	0.11	U	0.11	0.50	ug/L
8001-35-2	Toxaphene	1.70	U	1.70	10.0	ug/L
57-74-9	Chlordane	0.88	U	0.88	5.00	ug/L
SURROGATES						
2051-24-3	Decachlorobiphenyl	21.2		43 - 140	106%	SPK: 20
877-09-8	Tetrachloro-m-xylene	19.7		77 - 126	99%	SPK: 20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:	03/20/25	
Project:	DOT Harper Street Yard - North Side		Date Received:	03/21/25	
Client Sample ID:	GRID-LINE-1.2-NORTH		SDG No.:	Q1627	
Lab Sample ID:	Q1627-01		Matrix:	TCLP	
Analytical Method:	SW8081		% Solid:	0	Decanted:
Sample Wt/Vol:	100	Units: mL	Final Vol:	10000	uL
Soil Aliquot Vol:		uL	Test:	TCLP Pesticide	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	SW3541B				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PL094860.D	1	03/25/25 12:40	03/25/25 21:20	PB167311

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
58-89-9	gamma-BHC (Lindane)	0.037	U	0.037	0.50	ug/L
76-44-8	Heptachlor	0.027	U	0.027	0.50	ug/L
1024-57-3	Heptachlor epoxide	0.096	U	0.096	0.50	ug/L
72-20-8	Endrin	0.032	U	0.032	0.50	ug/L
72-43-5	Methoxychlor	0.11	U	0.11	0.50	ug/L
8001-35-2	Toxaphene	1.70	U	1.70	10.0	ug/L
57-74-9	Chlordane	0.88	U	0.88	5.00	ug/L
SURROGATES						
2051-24-3	Decachlorobiphenyl	23.7		43 - 140	119%	SPK: 20
877-09-8	Tetrachloro-m-xylene	19.8		77 - 126	99%	SPK: 20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit



LAB CHRONICLE

OrderID:	Q1627	OrderDate:	3/21/2025 1:34:14 PM
Client:	Tully Construction Co., Inc.	Project:	DOT Harper Street Yard - North Side
Contact:	Dean Devoe	Location:	I41

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1627-01	GRID-LINE-1.2-NORT H	TCLP			03/20/25			03/21/25
			TCLP Herbicide	8151A		03/25/25	03/26/25	
			TCLP Pesticide	8081B		03/25/25	03/25/25	



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.:Q1627

Order ID:Q1627

Client:Tully Construction Co., Inc.

Project ID:DOT Harper Street Yard - North Side

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
-----------	-----------	--------	-----------	---------------	---	-----	-----	-------

Client ID :

Total Concentration:0.000

A
B
C
D



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:		
Project:	DOT Harper Street Yard - North Side		Date Received:	03/25/25	
Client Sample ID:	PB167275TB		SDG No.:	Q1627	
Lab Sample ID:	PB167275TB		Matrix:	TCLP	
Analytical Method:	SW8151A		% Solid:	0	Decanted:
Sample Wt/Vol:	100	Units: mL	Final Vol:	10000	uL
Soil Aliquot Vol:		uL	Test:	TCLP Herbicide	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	8151A				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PS029602.D	1	03/25/25 12:23	03/28/25 05:15	PB167312

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
94-75-7	2,4-D	9.20	U	9.20	20.0	ug/L
93-72-1	2,4,5-TP (Silvex)	7.80	U	7.80	20.0	ug/L
SURROGATES						
19719-28-9	2,4-DCAA	528		39 - 175	106%	SPK: 500

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:	03/20/25	
Project:	DOT Harper Street Yard - North Side		Date Received:	03/21/25	
Client Sample ID:	GRID-LINE-1.2-NORTH		SDG No.:	Q1627	
Lab Sample ID:	Q1627-01		Matrix:	TCLP	
Analytical Method:	SW8151A		% Solid:	0	Decanted:
Sample Wt/Vol:	100	Units: mL	Final Vol:	10000	uL
Soil Aliquot Vol:		uL	Test:	TCLP Herbicide	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	8151A				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PS029592.D	1	03/25/25 12:23	03/28/25 00:51	PB167312

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
94-75-7	2,4-D	9.20	U	9.20	20.0	ug/L
93-72-1	2,4,5-TP (Silvex)	7.80	U	7.80	20.0	ug/L
SURROGATES						
19719-28-9	2,4-DCAA	466		39 - 175	93%	SPK: 500

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit



LAB CHRONICLE

OrderID:	Q1627	OrderDate:	3/21/2025 1:34:14 PM
Client:	Tully Construction Co., Inc.	Project:	DOT Harper Street Yard - North Side
Contact:	Dean Devoe	Location:	I41

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1627-01	GRID-LINE-1.2-NORT H	TCLP			03/20/25			03/21/25
			TCLP Herbicide	8151A		03/25/25	03/28/25	
			TCLP Pesticide	8081B		03/25/25	03/25/25	



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.:	Q1627	Order ID:	Q1627
Client:	Tully Construction Co., Inc.	Project ID:	DOT Harper Street Yard - North Side

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID :	GRID-LINE-1.2-NORTH							
Q1627-01	GRID-LINE-1.2-NORTH	TCLP	Barium	784		62.8	500	ug/L



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.	Date Collected:	03/20/25
Project:	DOT Harper Street Yard - North Side	Date Received:	03/21/25
Client Sample ID:	GRID-LINE-1.2-NORTH	SDG No.:	Q1627
Lab Sample ID:	Q1627-01	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	34.8	U	1	34.8	100	ug/L	03/25/25 12:05	03/26/25 12:10	SW6010	SW3050
7440-39-3	Barium	784		1	62.8	500	ug/L	03/25/25 12:05	03/26/25 12:10	SW6010	SW3050
7440-43-9	Cadmium	0.94	U	1	0.94	30.0	ug/L	03/25/25 12:05	03/26/25 12:10	SW6010	SW3050
7440-47-3	Chromium	6.60	U	1	6.60	50.0	ug/L	03/25/25 12:05	03/26/25 12:10	SW6010	SW3050
7439-92-1	Lead	35.1	U	1	35.1	60.0	ug/L	03/25/25 12:05	03/26/25 12:10	SW6010	SW3050
7439-97-6	Mercury	0.76	U	1	0.76	2.00	ug/L	03/25/25 12:16	03/26/25 09:09	SW7470A	
7782-49-2	Selenium	58.8	U	1	58.8	100	ug/L	03/25/25 12:05	03/26/25 12:10	SW6010	SW3050
7440-22-4	Silver	5.80	U	1	5.80	50.0	ug/L	03/25/25 12:05	03/26/25 12:10	SW6010	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	Q1627	OrderDate:	3/21/2025 1:34:14 PM
Client:	Tully Construction Co., Inc.	Project:	DOT Harper Street Yard - North Side
Contact:	Dean Devoe	Location:	I41

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1627-01	GRID-LINE-1.2-NORT H	TCLP			03/20/25			03/21/25
			TCLP ICP Metals	6010D		03/25/25	03/26/25	
			TCLP Mercury	7470A		03/25/25	03/26/25	



SAMPLE DATA

A

B

C

Report of Analysis

Client:	Tully Construction Co., Inc.	Date Collected:	03/20/25 12:30
Project:	DOT Harper Street Yard - North Side	Date Received:	03/21/25
Client Sample ID:	GRID-LINE-1.2-NORTH	SDG No.:	Q1627
Lab Sample ID:	Q1627-01	Matrix:	SOIL
		% Solid:	85.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	10.8	H	1	0	0	pH		03/24/25 17:05	9045D
Ignitability	NO		1	0	0	oC		03/24/25 11:45	1030
Reactive Cyanide	0.0086	J	1	0.0083	0.050	mg/Kg	03/25/25 11:30	03/25/25 15:45	9012B
Reactive Sulfide	6.31	J	1	0.20	10.0	mg/Kg	03/25/25 09:20	03/25/25 11:38	9034

Comments: pH result reported at temperature 22.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	Q1627	OrderDate:	3/21/2025 1:34:14 PM
Client:	Tully Construction Co., Inc.	Project:	DOT Harper Street Yard - North Side
Contact:	Dean Devoe	Location:	I41

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1627-01	GRID-LINE-1.2-NORTH	SOIL			03/20/25 12:30			03/21/25
			Corrosivity	9045D			03/24/25 17:05	
			Ignitability	1030			03/24/25 11:45	
			Reactive Cyanide	9012B		03/25/25	03/25/25 15:45	
			Reactive Sulfide	9034		03/25/25	03/25/25 11:38	