

## LAB CHRONICLE

|                 |                              |                   |                                     |
|-----------------|------------------------------|-------------------|-------------------------------------|
| <b>OrderID:</b> | Q1627                        | <b>OrderDate:</b> | 3/21/2025 1:34:14 PM                |
| <b>Client:</b>  | Tully Construction Co., Inc. | <b>Project:</b>   | DOT Harper Street Yard - North Side |
| <b>Contact:</b> | Dean Devoe                   | <b>Location:</b>  | I41                                 |

| LabID    | ClientID            | Matrix | Test             | Method | Sample Date       | Prep Date | Anal Date         | Received |
|----------|---------------------|--------|------------------|--------|-------------------|-----------|-------------------|----------|
| Q1627-01 | GRID-LINE-1.2-NORTH | SOIL   |                  |        | 03/20/25<br>12:30 |           |                   | 03/21/25 |
|          |                     |        | Corrosivity      | 9045D  |                   |           | 03/24/25<br>17:05 |          |
|          |                     |        | Ignitability     | 1030   |                   |           | 03/24/25<br>11:45 |          |
|          |                     |        | Reactive Cyanide | 9012B  |                   | 03/25/25  | 03/25/25<br>15:45 |          |
|          |                     |        | Reactive Sulfide | 9034   |                   | 03/25/25  | 03/25/25<br>11:38 |          |