

Initial and Continuing Calibration Verification

Client: Tully Construction Co., Inc.

SDG No.: Q1627

Project: DOT Harper Street Yard - North Side

RunNo.: LB135166

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Corrosivity	pH	7.00	7	100	90-110	03/24/2025
Sample ID: CCV1 Corrosivity	pH	2.01	2.00	101	90-110	03/24/2025
Sample ID: CCV2 Corrosivity	pH	12.02	12.00	100	90-110	03/24/2025
Sample ID: CCV3 Corrosivity	pH	2.01	2.00	101	90-110	03/24/2025

Initial and Continuing Calibration Verification

Client: Tully Construction Co., Inc.

SDG No.: Q1627

Project: DOT Harper Street Yard - North Side

RunNo.: LB135179

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.094	0.099	95	85-115	03/25/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025
Sample ID: CCV4 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	03/25/2025