



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,  
Fax : 908 789 8922

### Laboratory Control Sample/Laboratory Control Sample Duplicate Summary

SW-846

SDG No.: Q1627

Client: Tully Construction Co., Inc.

Analytical Method: **8081B** Datafile : PL094898.D

| Lab Sample ID | Parameter           | Spike | Result | Units | Rec | RPD | Qual | RPD  |     | Limits |     |
|---------------|---------------------|-------|--------|-------|-----|-----|------|------|-----|--------|-----|
|               |                     |       |        |       |     |     |      | Qual | Low | High   | RPD |
| PB167311BS    | gamma-BHC (Lindane) | 0.5   | 0.50   | ug/L  | 100 |     |      |      | 82  | 129    |     |
|               | Heptachlor          | 0.5   | 0.47   | ug/L  | 94  |     |      |      | 79  | 127    |     |
|               | Heptachlor epoxide  | 0.5   | 0.48   | ug/L  | 96  |     |      |      | 81  | 124    |     |
|               | Endrin              | 0.5   | 0.50   | ug/L  | 101 |     |      |      | 81  | 128    |     |
|               | Methoxychlor        | 0.5   | 0.51   | ug/L  | 102 |     |      |      | 78  | 108    |     |