

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client: PSEG Date Collected: 03/24/25 09:50

Project: Sewaren Laydown Yard Date Received: 03/24/25

Client Sample ID: VNJ-206 SDG No.: Q1630
Lab Sample ID: Q1630-02 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.82	Н	1	0	0	pН		03/24/25 17:10	9045D
Ignitability	NO		1	0	0	oC		03/25/25 15:30	1030
Reactive Cyanide	0.011	J	1	0.0084	0.050	mg/Kg	03/25/25 11:30	03/25/25 15:45	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	03/25/25 09:20	03/25/25 11:41	9034

Comments: pH result reported at temperature 23.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits