

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 03/25/25 12:22 Project: Clifton Gas Date Received: 03/25/25 Client Sample ID: 030825-COMP SDG No.: Q1643 Lab Sample ID: Q1643-04 Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.50	Н	1	0	0	pН		03/26/25 15:47	9045D
Ignitability	NO		1	0	0	oC		03/26/25 11:38	1030
Reactive Cyanide	0.0085	J	1	0.0083	0.050	mg/Kg	03/26/25 09:00	03/26/25 12:41	9012B
Reactive Sulfide	4.74	J	1	0.20	10.0	mg/Kg	03/27/25 09:30	03/27/25 12:43	9034

Comments: pH result reported at temperature 24.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits