

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:PSEGDate Collected:03/25/25 13:45Project:NYE Avenue SubstationDate Received:03/25/25

Client Sample ID: TP-1 SDG No.: Q1645

Lab Sample ID: Q1645-08 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.83	Н	1	0	0	pН		03/26/25 15:55	9045D
Ignitability	NO		1	0	0	oC		03/26/25 12:15	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	03/26/25 09:00	03/26/25 12:41	9012B
Reactive Sulfide	3.19	J	1	0.20	10.0	mg/Kg	03/27/25 09:30	03/27/25 12:48	9034

Comments: pH result reported at temperature 24.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits