

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 03/25/25 11:55 Project: Central Ave Substation Date Received: 03/25/25 Client Sample ID: TP-4 SDG No.: Q1648 Lab Sample ID: Q1648-01 Matrix: SOIL % Solid: 87.3

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigl	nt) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.46	U	1	0.080	0.46	mg/Kg	03/26/25 12:00	03/26/25 15:31	7196A
Ignitability	NO		1	0	0	oC		03/27/25 10:00	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		03/27/25 09:40	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits