

## **Report of Analysis**

Client:	Weston Solutions, Inc.		Date Collecte	d: 03/26/25 09:45	
Project:	RFP 905		Date Receive	d: 03/27/25	
Client Sample ID:	P001-BBDGA-004-01		SDG No.:	Q1664	
Lab Sample ID:	Q1664-14		Matrix:	WATER	
			% Solid:	0	
Parameter	Conc. Qua. DF MDL	LOQ / CRQL	Units Prep Da	te Date Ana. Ana Met.	
Cyanide	0.0014 J 1 0.00096	0.0050	mg/L 03/31/25	2:00 03/31/25 14:38 9012B	

Comments:

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

- J = Estimated Value
- B = Analyte Found in Associated Method Blank
- \* = indicates the duplicate analysis is not within control limits.
- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits