

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Weston Solutions, Inc. Date Collected: 03/26/25 10:00 Project: RFP 905 Date Received: 03/27/25 Client Sample ID: P001-BBDGA-007-01 SDG No.: Q1664 Lab Sample ID: Q1664-20 Matrix: WATER % Solid: 0

| Parameter | Conc. Qua. | DF MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|------------|-----------|------------|-------|----------------|----------------|----------|
| Cyanide | 0.0013 J | 1 0.00096 | 0.0050 | mg/L | 03/31/25 12:00 | 03/31/25 14:44 | 9012B |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits