

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 03/27/25 12:00 Project: NYE Avenue Substation Date Received: 03/27/25 Client Sample ID: TP-8 SDG No.: Q1672 Lab Sample ID: Q1672-04 Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.52	Н	1	0	0	pН		03/28/25 16:40	9045D
Ignitability	NO		1	0	0	oC		03/31/25 11:15	1030
Reactive Cyanide	0.017	J	1	0.0083	0.050	mg/Kg	03/31/25 10:00	03/31/25 12:30	9012B
Reactive Sulfide	6.37	J	1	0.20	10.0	mg/Kg	03/31/25 13:50	03/31/25 16:09	9034

Comments: pH result reported at temperature 22.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits