

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

% Solid:

100

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 03/28/25 09:22 Project: Sewaren Laydown Yard Date Received: 03/28/25 Client Sample ID: 72-11991 SDG No.: Q1674 Lab Sample ID: Q1674-04 Matrix: **SOIL** 

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.60	Н	1	0	0	рН		03/28/25 16:50	9045D
Ignitability	NO		1	0	0	oC		03/31/25 11:45	1030
Reactive Cyanide	0.014	J	1	0.0083	0.050	mg/Kg	03/31/25 10:00	03/31/25 12:30	9012B
Reactive Sulfide	4.76	J	1	0.20	10.0	mg/Kg	03/31/25 13:50	03/31/25 16:15	9034

Comments: pH result reported at temperature 25.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits