

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 04/01/25 11:35 Project: 26kV 40-50 Seaview Permanent OP Date Received: 04/01/25 Client Sample ID: WCS-TP-1 SDG No.: Q1693 Lab Sample ID: Q1693-09 Matrix: SOIL % Solid: 78.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	it) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.51	U	1	0.088	0.51	mg/Kg	04/02/25 11:25	04/02/25 16:46	7196A
Ignitability	NO		1	0	0	oC		04/02/25 14:08	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		04/02/25 09:52	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits