

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: JACOBS Engineering Group, Inc. Date Collected: 04/01/25 15:30

Project: Former Schlumberger STC PTC Site # D3868221 Date Received: 04/01/25

Client Sample ID: IW-03-55-040125DL SDG No.: Q1697 Lab Sample ID: Q1697-05DL WATER

> % Solid: 0

Matrix:

Parameter	Conc.	Qua.	DF MI	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	12.5	D	5 0.9	3.00	mg/L		04/02/25 16:18	9056A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits