

Initial and Continuing Calibration Verification

Client: Tully Construction Co., Inc.

SDG No.: Q1698

Project: MTA Rockaway Park

RunNo.: LB135276

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.01	7	100	90-110	04/02/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90-110	04/02/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	04/02/2025

Initial and Continuing Calibration Verification

Client: Tully Construction Co., Inc.

SDG No.: Q1698

Project: MTA Rockaway Park

RunNo.: LB135312

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.094	0.099	95	85-115	04/04/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	04/04/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	04/04/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	04/04/2025

Initial and Continuing Calibration Verification

Client: Tully Construction Co., Inc.

SDG No.: Q1698

Project: MTA Rockaway Park

RunNo.: LB135312

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------