

Initial and Continuing Calibration Blank Summary

Client: Tully Construction Co., Inc.

SDG No.: Q1698

Project: MTA Rockaway Park

RunNo.: LB135312

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB1 Reactive Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	04/04/2025
Sample ID: CCB1 Reactive Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	04/04/2025
Sample ID: CCB2 Reactive Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	04/04/2025
Sample ID: CCB3 Reactive Cyanide	mg/L	< 0.0025	0.0025	U	0.00096	0.005	04/04/2025

Initial and Continuing Calibration Blank Summary

Client: Tully Construction Co., Inc.

SDG No.: Q1698

Project: MTA Rockaway Park

RunNo.: LB135312

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
---------	-------	--------	----------------------	--------------	-----	-----	------------------