

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Tully Environmental, Inc Date Collected: 04/01/25 14:00

Project: Transfer Station - SPDES 2025 Date Received: 04/02/25

Client Sample ID: 001-WILLETS-PT-BLVD(MAR) SDG No.: Q1707

Lab Sample ID: Q1707-01 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua	. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TSS	54.0	1 1.00	4.00	mg/L		04/03/25 09:30	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits