

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 04/03/25 10:36 Project: Aubudon Gas District Date Received: 04/03/25 Client Sample ID: GAS-AUD-25-0037 SDG No.: Q1723 Lab Sample ID: Q1723-04 Matrix: SOIL % Solid: 98

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ignitability	NO		1	0	0	oC		04/04/25 15:02	1030
pН	6.46	Н	1	0	0	pН		04/04/25 09:44	9045D

Comments: pH result reported at temperature 25.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits