

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PARSONS Engineering of New York, Inc. Date Collected: 04/04/25 09:40

Project: Con Edison - 11th Ave-West 50th St Site Date Received: 04/04/25

Client Sample ID: WC-LIQUID-20250404 SDG No.: Q1739

Lab Sample ID: Q1739-02 Matrix: Water

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Flash Point	>212		1	0	0	o F		04/08/25 10:15	1010B
pН	6.53	Н	1	0	0	pН		04/07/25 16:56	9040C
Reactive Cyanide	0.00096	U	1	0.00096	0.0050	mg/L	04/07/25 15:00	04/08/25 11:28	9012B
Reactive Sulfide	0.43	U	1	0.43	1.00	mg/L	04/08/25 12:50	04/08/25 15:38	9034

Other method reference for flash point: Pensky-Martens Closed Cup Flash Point ASTM D 93 - IP 34, pH result reported at temperature

U = Not Detected

Comments:

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits