

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: CHA Companies, Inc. Date Collected: 04/09/25 09:20 Project: Date Received: NYSOMH Emergency Service 04/09/25 Client Sample ID: B2-W8-RM1016-SINK SDG No.: Q1759 Lab Sample ID: Q1759-01 Matrix: Water % Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Residual Chlorine	0.26	Н	1	0.023	0.10	mg/L		04/10/25 09:26	SM 4500-C1 G-11
Turbidity	2.30		1	0.15	1.00	NTU		04/10/25 14:36	SM 2130 B-11

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits