



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: CHA Companies, Inc.

SDG No.: Q1759

Project: NYSOMH Emergency Service

RunNo.: LB135364

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Residual Chlorine	mg/L	0.396	0.4	99	90-110	04/10/2025
Sample ID: CCV1 Residual Chlorine	mg/L	0.391	0.4	98	90-110	04/10/2025
Sample ID: CCV2 Residual Chlorine	mg/L	0.380	0.4	95	90-110	04/10/2025
Sample ID: CCV3 Residual Chlorine	mg/L	0.370	0.4	92	90-110	04/10/2025

Initial and Continuing Calibration Verification

Client: CHA Companies, Inc.

SDG No.: Q1759

Project: NYSOMH Emergency Service

RunNo.: LB135374

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Turbidity	ICV	NTU	9.821	10	98	90-110	04/10/2025
Sample ID: Turbidity	CCV1	NTU	9.479	10	95	90-110	04/10/2025
Sample ID: Turbidity	CCV2	NTU	9.428	10	94	90-110	04/10/2025