

Report of Analysis

| | | | |
|-------------------|----------------------------------|-----------------|----------------|
| Client: | Parkway Generation Operating LLC | Date Collected: | 04/10/25 09:28 |
| Project: | Linden Generating Station - LRSA | Date Received: | 04/10/25 |
| Client Sample ID: | DSN002 | SDG No.: | Q1766 |
| Lab Sample ID: | Q1766-02 | Matrix: | WATER |
| | | % Solid: | 0 |

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|-------|------|----|-----|------------|-------|-----------|----------------|------------|
| Field pH | 7.48 | | 1 | 0 | 0 | pH | | 04/10/25 09:34 | SM4500-H B |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits