

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Parkway Generation Operating LLC Date Collected: 04/10/25 12:00

Project: Linden Generating Station - LRSA Date Received: 04/10/25

Client Sample ID: DSN001 SDG No.: Q1766 Lab Sample ID: Q1766-03 WATER

> % Solid: 0

Matrix:

Parameter	Conc. Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
BOD5	33.6	1	0.20	2.00	mg/L		04/10/25 16:20	SM 5210 B-16
COD	143	1	1.50	10.0	mg/L		04/16/25 14:54	SM 5220 D-11
TSS	43.2	1	1.00	4.00	mg/L		04/11/25 09:40	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits