

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Lockwood, Kessler & Bartlett, Inc. Date Collected: 04/09/25 11:30

Project: Ansonia Landfill 2025 Date Received: 04/10/25

Client Sample ID: MW-3DL SDG No.: Q1782
Lab Sample ID: Q1782-05DL Matrix: WATER

% Solid: 0

Parameter	Conc. Qu	ua. DF MDL	LOQ / CRQL	Units P	Prep Date	Date Ana.	Ana Met.
Chloride	391 I	D 100 19.0	60.0	mg/L		04/11/25 15:20	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits